# General Environmental Incident Summary

Incident: 3777 Date/Time Notice: 6/11/2015 DEM Incident No:

Responsible Party: Montana-Dakota Utilities Co.

Date Incident:6/9/2015Time Incident:10:36Duration:County:BurleighTwp:139Rng:80Sec:32Qtr:Lat:46.82025Long:-100.81510Method:Interpolation from map

Location Description: Mystic Hall

1309 Schafer Street Bismarck, ND 58501

Submitted By: Andy McDonald Affiliation:

Address: 400 N 4th St.

City: Bismarck State: ND Zip:

Received By:
Contact Person:

400 N 4th St.

Bismarck, ND 58501

Distance Nearest Occupied Building: 10 Feet Release Contained: Yes

*Type of Incident:* Transformer Leak

Description of Released Contaminant: Less than one gallon of mineral oil (test for PCB content

is being conducted and we will provide results as they

become available to us)

Volume Spilled: 1.00 gallons Ag Related: No EPA Extremely Hazardous Substance: No Reported to NRC: No

## Cause of Incident:

Emily Tintes Schiwal with NDDoH reported this incident to Montana-Dakota at 10:36 AM as noted above, while inspecting BSC electrical equipment. The leaking transformer was identified as Montana-Dakota's. Montana-Dakota dispatched a crew which found small leak on back right hand side of bottom seal.

## Risk Evaluation:

None

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

## Potential Environmental Impacts:

Expected to be minimal due to small amount of oil spilled.

#### Action Taken or Planned:

Spill was less than one gallon. Soil and grass were excavated with a one foot buffer from visual contamination. Transformer and pad were removed. The clean-up was completed by 14:30 on June 9.

Wastes Disposal Location: Contaminated materials were taken back to PCB building in Bismarck.

# Agencies Involved:

# **Updates**

Date: 6/11/2015 Status: Reviewed - Assigned to NDDoH Division Author: Crowdus, Kory

**Updated Volume:** 

### Notes:

Release from a transformer on the Bismarck State College campus. Report forwarded to the Waste Management division.

Date: 6/12/2015 Status: Inspection Author: Tintes Schiwal, Emily

# **Updated Volume:**

### Notes:

I discovered the oil leak during a PCB inspection of the electrical equipment on Bismarck State College's campus. BSC owns most of the transformers on campus, but believed this one belonged to Montana Dakota Utilities. I called MDU and emailed over the photos immediately after my inspection on 06.09.15. MDU confirmed they owned the unit, and they sent a crew to replace it within a few hours of my notification. Test results were returned today, 06.12.15, and the unit's mineral oil has 0ppm PCB content. I took initial photos and returned today to take photos of the new unit and excavated area. After doing a follow up inspection and getting the PCB testing results, no further action is required on this incident. Photos and test results are in the corresponding folder.